

CEN23LA298

## **INVESTIGATION PHOTOGRAPHS**

PG 1 OF 2



Photograph 1 - Damaged Wings (Courtesy of Lino Lakes Public Safety)